

# MK MACHINING



## ***Gen II T-Post Target Mount Instructions***

**Slide mount over T-Post (it will only fit in the correct position) and tighten single 1/2-13 bolt. This fits a 3/4" wrench or another mount can be used. For a mount that won't be moved much, Loctite can provide a more permanent grip. Place the spring in between the target and mount, and tighten to put the target under tension, but do not fully compress the spring.**

**An adapter & "wing" can be bolted onto the vertically spaced holes for large or multiple targets. Now you're ready to go ring steel!**